

## IMPORTANT SAFETY NOTICE

**\* TO BE POSTED IN A LOCATION VISIBLE TO CONSUMERS FOR 120 DAYS FROM AUGUST 20, 2008 \***

# VOLUNTARY RECALL NOTICE

## TRUE TEMPER WOLF SL BICYCLE FORK ON CERVÉLO BICYCLES

Cervélo has identified a potential safety issue involving the fork steerer which can crack and eventually break during normal use, causing the rider to lose control, fall and suffer serious injuries. Therefore, Cervélo is voluntarily recalling all True Temper Wolf SL carbon bicycle forks.

Although the Wolf SL carbon bicycle fork passed all the standard industry tests, this particular problem was not uncovered during those standard tests. Cervélo has now discontinued the use of the True Temper Wolf SL carbon bicycle fork.

**Description:** The recalled forks have a clear coating over black painted carbon fiber, with the words "Wolf Superlite" and related logo just below the crown on each fork leg, and the words "SL" on each leg above the fork blade dropouts. There is a True Temper CRT™ logo on the inside of both fork legs. The recalled forks could have been included on the following bicycle models: R3, R3 SL, Soloist Carbon, Soloist Carbon SL, and certain P3 Carbon framesets and complete bicycles. The True Temper Wolf SL carbon fiber bicycle fork subject to this recall were sold through independent bicycle retailers in the US from November 2005 through July 2008 as an OEM specified component on some units of the following Cervélo bicycle models: R3, R3 SL, Soloist Carbon, Soloist Carbon SL, and certain P3 Carbon framesets and complete bicycles. It was also sold through independent bicycle retailers in the US as an individual after-market item from November 2005 through June 2007. This recall only applies to Wolf SL forks. The Wolf TT or CL forks are not included.

**Remedy:** Consumers should immediately stop using bicycles equipped with the recalled forks and contact their authorized Cervélo dealer (using the site below) to have a free replacement fork installed. Recalled True Temper Wolf SL forks will be replaced with the 3T Funda Pro or the Easton EC90SLX fork. Replacement forks will be provided free of charge to the consumer. The 3T Funda forks will require the steerer to be cut to appropriate length and aluminum insert to be bonded into the steerer. All labor charges associated with this work will be covered by Cervélo.



[www.cervelo.com/WolfSLrecall](http://www.cervelo.com/WolfSLrecall) email: [WolfSLRecall@cervelo.com](mailto:WolfSLRecall@cervelo.com)  
Toll Free Recall Hotline: 1-866-296-3137 10am to 5pm EST M-F